


Remote Motor Run / Interface Cable

922-040, 120 VAC, XP-922-040, <mark>220</mark> VAC

System ReadyCable

922-121, 120 VAC, X922-121, 220 VAC

Automatic gun applications



After the gun has completed its pattern, both the gun and the motor are turned off simultaneously.

Automatic or Manual applications (using hose only)

Level Sensor

Hot Melt Bath

OEM Supplied Motor ON/OFF (Contact Closure)

Example

When the hot melt bath drops below the required level, the motor is activated to pump material into the bath.

When the bath has reached the appropriate level, the motor is turned off and the system stops filling.

